

# Tsunami Impacts to Lifelines:

*Review of Current Knowledge and Post-Event Survey of the 16 September 2015*

*M8.3 Illapel, Chile Tsunami*

Nick Horspool, Stuart Fraser (GNS Science)  
Richard Mowll (Wellington Lifelines Group)





**Chile Survey Team:**

- Ryan Paulik (NIWA)
- Richard Woods (Auckland CDEM)
- James Williams (University of Canterbury)




## New Zealand's Tsunami Hazard

- 10 tsunami with coastal heights over 5m since 1840
- Most prior to significant coastal development




## 100 Year Return Period Tsunami Heights




GNS Science

## 500 Year Return Period Tsunami Heights



GNS Science

## 2500 Year Return Period Tsunami Heights



GNS Science

### Key Tsunami Characteristics Related To Damage

- Can affect large areas of coast
- High flow velocities (30 cm can knock over an adult)
- Large amount of debris (vegetation, vehicles, buildings)
- Sediment deposition
- Salt water contamination and corrosion
- Multiple waves with inward and outward flows
- Wave period can be 10-20 minutes between peaks
- Significant scouring
- Large forces in both directions:
  - lateral hydrodynamic forces (seismic design)
  - vertical buoyancy forces (not designed for)

GNS Science



GNS Science

## The ALG/WeLG Tsunami Impacts Project

- WeLG/ALG commissioned GNSby to:
  - Summarise literature on tsunami impacts to lifelines into a format suitable for NZ lifelines
- Project oversight by ALG/WeLG Steering Committee
- Aim to include information from major events:
  - Indian Ocean Tsunami (2004)
  - Chile (2010)
  - **Japan (2011)**
- Draft reports April 2015/July 2015
- Impact tables developed in August 2015 (replacing posters)
- Incorporate new findings from 2015 Chile Survey

GNS Science




## 16 September 2015 M8.3 Illapel, Chile Earthquake and Tsunami

- Survey: Sat 26<sup>th</sup> Sept – Mon 5<sup>th</sup> Oct (10 days after event)
- Included: GNS, NIWA and Auckland Council staff, one consultant and one University of Canterbury Masters student
- Funding: GNS/NIWA RiskScape, EQC, NZSEE, AC, UC
- Local support from CIGIDEN
- Main investigations carried out in Coquimbo
- Lifelines assets reviewed:
  - Electrical
  - Roads, footpaths, rail
  - Port and wharves
  - Water(s)
  - Seawalls

GNS Science

## 16 September M<sub>w</sub>8.3 Illapel, Chile Earthquake



GNS Science



## ShakeMap



GNS Science

**Coquimbo – Port Town of 200k people**  
600m inundation extent, 6m run up, 5m flow depth



GNS Science

## Survey Method

- Lifeline damage survey
  - 2 x 2 person teams (one lifeline per team)
  - Used Real-Time Asset Capture Tool (RiACT) tablets
  - Census style data collection (all assets in inundation zone were surveyed)
  - Tsunami water marks recorded
  - Meetings with electricity and water companies
  - Aim to develop tsunami vulnerability models
- Summary statistics:
  - ~600 high quality water marks
  - > 3,000 assets surveyed

GNS Science



GNS Science






GNS Science



GNS Science

## Coquimbo



### Electrical – ALG/WeLG report findings

- This sector is under-represented in literature on damage to lifelines in tsunami
- Little information on underground services
- Generic information on tsunami effects on poles exists
- Little information on effects to substations and transformers
- No fragility curves could be derived from the information

## Electrical – Coquimbo findings

- There were no transmission assets in the tsunami zone
- There were minimal buried cables in the tsunami zone
- The distribution network was largely overhead
- Data was captured for:
  - Power poles
  - Street lights
  - Substation(?)
- Information gathered from Conafe (local lines company)
- Overhead lines/pole mounted transformers were washed away if tsunami reached them
- Pole failure from shearing at base, debris strike, scouring at foundations

GNS Science



GNS Science



GNS Science



GNS Science





GNS Science



GNS Science



GNS Science



GNS Science





GNS Science



GNS Science

## Electrical – Coquimbo findings

- Aspects from Conafe (local lines company):
  - Distribution lines were heavily impacted in tsunami zone
  - Increased staff from 50 (BAU) to use 550 staff over the six days following the tsunami
  - 40 HV crews and 140 LV crews worked
  - Their key was to have a logistics plan in place to support the inflow of staff
  - Planners worked nights and provided crews plans/tasks for the days. Handovers were at 7am/7pm
  - All distribution lines assets were recovered within 6 days
  - Conafe staff had no ‘Lost Time Injuries’
  - Conafe extended their mandate to install two working lights within each household

GNS Science

## Increasing Resilience

- Buried lines are less vulnerable than overhead lines unless cable housing damaged by earthquake
- Locate substations outside of tsunami inundation zones
- Outside substations are more vulnerable than internal ones, particularly for washout
- Stockpile spares (electrical components, poles etc) for rapid repairs
- Have a plan for response – larger than BAU

GNS Science

## Roads – ALG/WeLG report findings

Damage and failure modes:

- Debris, sediment deposits and flooding are common throughout inundation zone after tsunami withdraw
- Debris size is related to flow depth and available debris (vegetation, vessels, vehicles, buildings)
- Scouring, often on roads near coast, on raised embankments or changes in slope (focussed flow)

GNS Science

## Roads – Coquimbo findings

- Most observations (below) from a 0-5m flow depth
- Debris and flooding present after tsunami
- Most roads in the inundation zone were founded on sandy material, with a granular base and a thin asphalt surface
- There were very few ‘both-lane’ wash-outs (by the sea)
- There were many minor / single lane wash-outs (by the sea)
- All wash outs were where culverts ran under road to sea
- Most roads away from the sea/drainage features were relatively unaffected

GNS Science



GNS Science







GNS Science



GNS Science



## Increasing Resilience

- Introduce redundancy in network
- Strengthen and protect coastal roads at sites of culverts or outflows with rip rap
- Develop arrangements with contractors to clear debris repair scoured sections
- Use well engineered road bases



## Ports and Wharves – ALG/WeLG Report

Can be affected by very small tsunami and strong flow velocities (marine threat events)

Damage and failure modes:

- Damage to wharf decks and piers (buoyancy forces and lateral loads)
- Scour of piers and seawalls/breakwaters
- Damage to wharf buildings
- Damage to vessels from entrainment in flow
- Significant source of debris – vessels, containers etc

GNS Science

## Port and wharves – Coquimbo findings

- Wharves relatively unaffected by tsunami (higher levels of earthquake damage likely)
- Operations heavily affected by floating debris

GNS Science



GNS Science



GNS Science



GNS Science



GNS Science



GNS Science



GNS Science



GNS Science



## Increasing Resilience

- Strengthen ties between piers and decks to resist buoyancy forces
- Develop response plan for large vessels to exit to deep water (~150m depth)
- Some evidence 'bumpers' can reduce impact forces from debris/vessel strikes
- Evacuation plan for port/wharf personnel

GNS Science

## Fuel Tanks/Depots

Damage and failure modes:

- Damage to pipe connections ( > 2 m)
- Scour of tank foundation
- Buckling of base of tank
- Floatation and entrainment ( > 2m) dependent on capacity and fullness
- Fire following

GNS Science





GNS Science



GNS Science



GNS Science



GNS Science

## Increasing Resilience

- Large capacity tanks are less likely to slide and float
- Relocate tanks outside of tsunami inundation zone
- Construct scour resistant foundations
- Construct tanks to seismic design standards to resist lateral loads
- Locate tanks away from sources of debris
- Minimize low levels of fuel in tank

GNS Science

## Bridges - ALG/WeLG report findings

- Bridges are often vulnerable hot spots in transport and other lifelines networks

Damage and failure modes:

- Most bridges will experience scouring around wing walls, usually more severe on landward side from tsunami withdraw (higher velocities) and at base of piers
- Debris deposition on deck
- Debris strikes cause damage to superstructure
- Earthquake engineered bridges perform well under lateral tsunami loads but not designed for buoyancy forces on superstructure from tsunami which leads to washout (> 2m above deck)

GNS Science

## Bridges - Coquimbo findings

- RC four-lane multi-span bridge
- Bridge was overtopped by 1m flow depths
- Superstructure undamaged
- Minor-moderate scour of unprotected wing-walls on all four sides. More severe on landward side.
- Failure of services on landward side of bridge from scour

GNS Science



GNS Science



GNS Science



GNS Science





GNS Science



GNS Science



GNS Science



GNS Science

## Increasing Resilience

- Design longer wingwalls to reduce scour
- Use deeper pier foundations to reduce effect of scour
- Design with lower profile to reduce hydrodynamic drag and chance of debris strike
- Strengthen connections between piers and superstructure to resist buoyancy forces
- RC/PC perform better than steel or steel truss
- Bury services instead of attaching to bridge

GNS Science

## Rail - ALG/WeLG report findings

Damage and failure modes:

- Ballast and rail embankments are sites of scour
- Rail tracks can be shifted laterally in < 1 m of water
- Train carriages were observed to float in as little as 1.7 m of flowing water
- Overhead lines and ground based switches can be shorted upon contact with tsunami flow and are often washed away
- Overhead line poles can be damaged from strong flows or debris strikes

GNS Science

## Rail – Coquimbo Survey

- Single track in inundation area
- On wooden sleepers
- Shifted laterally in <1 m flow depths
  - 200 m length
- Washed away in > 2 m flow depths
  - 800 m length
- Minor scouring of ballast



GNS Science



GNS Science





GNS Science



GNS Science





GNS Science



GNS Science

## Increasing Resilience

- Develop contingency plan to clear debris from line, repair overhead lines, repair scour or washouts
- Stock pile of spares of electrical equipment
- Develop tsunami evacuation response plan for passengers on coastal lines
- Strengthen steel rail bridges in tsunami inundation zones

GNS Science

## Airports – ALG/WeLG Report

Damage and failure modes:

- Damage and flooding of terminal buildings
- Damage to low lying electrical equipment
- Floatation of vehicles and machinery
- Floatation of aircraft (no planes in Sendai airport)
- Scour of embankments (not runway tarmac)
- Debris deposition on runway
- Ponding of water on runway

GNS Science



GNS Science



GNS Science

## Increasing Resilience

- Primarily through recovery planning
- Develop plans for removing debris and pumping ponded water from runway
- Stockpile critical spare parts
- Plans for moving aircraft that have been floated
- Develop evacuation plan for passengers in terminal and onboard aircraft on tarmac based on maximum expected tsunami heights

GNS Science

## Water - ALG/WeLG report findings

Damage and failure modes:

- Treatment ponds can be contaminated if inundated
- Pump station electrical equipment and mechanical equipment vulnerable to flooding and sediment contamination or washout (>3m flow depth)
- Pipes are often scoured but undamaged
- Frequent weak points in pipe networks are where they cross bridges
- Wells and bores are easily contaminated if in inundation zone
- Outflows and drains are often clogged with debris and sediment and require significant cleaning

GNS Science



## Water – Coquimbo Survey

- Surveyed:
  - Manholes
  - Drains
  - Pump station (1)
  - Pipes (where visible)
- Potable water pipe broken at bridge from embankment scour. Rest of pipe scoured but not damaged.
- Main sewerage pump stations severely damaged. Back to 70% load in 2 weeks.
- Most drains blocked, but cleaned out 10 days later
- Culverts were points of weakness and most heavily damaged from scouring

GNS Science



GNS Science







GNS Science



GNS Science



GNS Science



GNS Science



GNS Science





## Increasing Resilience

- Locate water supply and treatment facilities outside of tsunami inundation zones;
- Construct facility buildings using reinforced concrete and ensure areas containing power systems are watertight, or locate electrical equipment at height to minimise damage to key electrical components;
- Install sealed lids on pumps and tanks to stop contamination by saltwater, sediment, and debris;
- Bury pipes across water crossings or attach to earthquake strengthened reinforced concrete bridges, preferably with protection buffers to reduce damage from debris impacts;
- Use watertight caps on wells

GNS Science

## Seawalls / washouts

Damage and failure modes:

- Significant sea wall washout can occur in flow depths  $>2$  m
  - $\sim 1$  km in length
- Seawalls suffered minor damage in flow depths  $< 1$  m
  - $> 3$  km in length
- No damage  $< 0.5$  m flow depth
- Sea wall failure often exposed road/footpath behind seawall for scour
- Significant scour of seawall occurred at sites of storm water outflows or culverts

GNS Science



## SeaWall Construction

- Large stone riprap
- Concrete conglomerate sloping and vertical wall
- Loose sand fill beneath



GNS Science



GNS Science



GNS Science



GNS Science



GNS Science



GNS Science






GNS Science

## Telecommunications – ALG/WeLG Report

### Damage and Failure Modes

- Cellular sites from debris strike or hydrodynamic forces on towers or collapse of buildings
- Exchanges from flooding or washout of building
- Buried cables entering buildings (scour around foundation)
- Buried cables from scour
- Power outages to cell sites/exchanges and depletion of backup batteries (2 hrs) and flooding of backup generators
- Washout and flooding of submarine cable landing sites

GNS Science



GNS Science

## Damage to exchange buildings and PC poles







GNS Science





GNS Science



GNS Science

## Increasing Resilience

- Relocate exchanges/cell towers out of tsunami inundation zones or on upper floors of multi-storey reinforced concrete buildings
- Raise electrical equipment, switches and back up generators
- Bury cables across waterways rather than across bridges
- Use buried cables rather than overhead lines
- Install large radio base stations to use as back up for exchanges Increase battery life on cell sites and exchanges, possibly setting up alternate power sources (e.g., solar, wind etc.)
- Continued.....

GNS Science

## Increasing Resilience continued....

- Have a stockpile of mobile cell sites, generators and radio repeaters that can be deployed to areas with service outages
- Develop short voice messaging system
- Deploy mobile WIFI hotspots that use satellite links

GNS Science

## Key Findings Across Lifeline Sectors

- Relocation of assets if possible is best mitigation option
- Electrical equipment is vulnerable and located near ground
- Back-up generators are often located on ground floors and also damaged
- Availability of spares critical to quick recovery
- Contingency plans for response
- Tsunami Hotspots for lifelines:
  - Coastal outflow sites and culverts → scour of coastal roads and loss of all below and above ground services
  - Bridges → scouring or washout causes loss of all services on bridge
  - Coastal sites with multiple lifelines (coastal road/rail/buried services or ports with fuel depots)

GNS Science

## Coastal State Highways

- Multiple lifelines services run along route
- Potentially vulnerable to scour and washout

SH2 Wellington



SH1 Kaikoura



GNS Science

## Seaview Fuel Terminal

- Significant source of debris from vessels
- Wellingtons main road fuel supply



GNS Science

## Landing of Cook Strait HVDC/Fibre Optic Cable



GNS Science

## Next Steps

- Update ALG/WeLG report and damage tables for with findings from Chile survey and release report
- Publish survey report for International Tsunami Information Centre (ITIC) and NZSEE
- Develop quantitative lifeline fragility models (probability of damage) to be used in tsunami impact/risk assessments using RiskScape

GNS Science

## TsuRGe – Tsunami Impacts Research Group

- Collective of researchers and stakeholders
- Raise awareness of tsunami impacts
- Coordinate research on tsunami impacts driven by end users (e.g. lifelines)
- Coordinate post-tsunami surveys and reconnaissance trips
- Plan to hold initial scoping workshop and draft ToR

*n.horspool@gns.cri.nz*

GNS Science